

ABSTRACT

A method of displaying a measurement result in an inspection process using network, the method includes a first step that a host, which intensively controls and manages a device for inspecting a lot to be processed in one or a plurality of steps, transmits to the device a condition of measuring a lot determined to be put in, a second step that the device measures the lot based on the measurement condition received via the network and then obtains measured data, a third step that the host determines whether the measured data received via the network is abnormal or normal based on a predetermined assessment standard and then produces a result of assessing a measured value so as to transmit the result to the device and a fourth step that the device provides a display corresponding to the result of assessing the measured value in accordance with the received result of assessing the measured value as well as a previously registered display standard.